



Photo 1 – View of damaged right wing lift strut and rudder of inverted airplane (Photo courtesy of the pilot)