



Photo 1 – View of damage to the tail rotor driveshaft, fuselage and main rotor blades (Courtesy of FAA)