



Photo 1 – View of damaged tailboom and trailer (courtesy of the FAA)



Photo 2 – View of landing zone (courtesy of the FAA)