

Record of Conversation

Saturday, May 24, 2014

Interview:	Don Hodges
Phone:	██████████
Location:	Telephone Conversation

Narrative:

The following is a summary of conversation with Mr Don Hodges, who was in the left seat of the airplane and is part owner of the airplane.

Mr Hodges stated that they were landing on runway 12, and Mr Frank Miles was flying the airplane. He said they were practicing short field/soft field landing. During the accident landing, they touched down, bounced, and the nose gear collapsed.

Mr Hodges stated that there was no preaccident mechanical failures or malfunctions of the airplane.

Van S. McKenny IV
Aerospace Engineer (Field)
Western Pacific Region