

Walter F Ramseur
[REDACTED]
Millbrae CA 94030 2200
August 5 2014

RECEIVED
AUG 11 2014
WP-FSDO (SJC)

Jehn Mathieu
Aviation Safety Inspector

On July 30 2014 I flew to Lampson Field (1o2) Lakeport Ca, after landing on RW 28 turning off to the left I had to push hard to get action from the left brake, During the turn off the idling engine quit. I restarted and taxied to the ramp. After about three hours of 100 degree weather I returned to and landed RW 30 at San Carlos (SQL) and turned left off the runway and in turning left onto the Taxi way the engine slowed and I added power to keep it running and had difficulty completing the turn due to ineffective braking, struck the wing tip of a parked airplane.

[REDACTED]

8/5/14