

WPR14FA209 Photographs



Photo 1. The airplane parked on the beach prior to takeoff, showing the left landing gear tied to the left wing lift-strut. (Courtesy Michael Robbins)



Photo 2. The airplane on the “step” during the final takeoff attempt. (Courtesy Robert Jacobson)



Photo 3. The airplane laying on the surface of the lake following the accident, the cabin is submerged.
(Courtesy Robert Jacobson)



Photo 4. Exterior view of the airplane's hull bottom wreckage, viewed from the aft step forward.



Photo 5. Interior view of the hull bottom wreckage.