

WPR14FA231 Photos



Photo 1. Fire and weather shortly after impact.



Photo 2. Tail of the airplane looking southwest.



Photo 3. Front of the airplane looking northeast.



Photo 4. View from the right wingtip looking south.



Photo 5. Right engine propeller blade.



Photo 6. Left engine propeller blade.



Photo 7. Left engine exhaust manifold.



Photo 8. Right engine exhaust manifold.



Photo 9. Left wing leading edge.