



Company Web Sites

Business Process

Field Reps

Engine Condition Report

100001433

Type of Call:
Telephone

All recommended adjustments are subject to TCM final approval after review of TCM analytical inspection finding.

Part Number:	649413	Description:	Crankcase
Date:	08/27/2002	Serial Number:	unknown
Date of Occurrence (mm/dd/yyyy):	08/01/2002	Model Number:	0-200
Claim Number:	NULL	Actual Total Hours:	91
Aircraft Make/Model:	Vari	Reg:	N S/N: unknown
Engine In-Service Date (mm/dd/yyyy):	07/12/2002	New:	N Rebuilt:
Component In-Service Date (mm/dd/yyyy):	07/12/2002		
Dealer or FBO:	Light Speed Engineering	Phone:	805-933-3299
Address:	416 East Santa Maria St. Hangar 15	Fax:	805-525-0199
Owners Name:	Joseph Moore	Phone:	
Distributor:	Aero		
Engine Component:	CRANKCASE		
Engine Component 2:	CASTING		
Engine Component 3:	CRACKED		

Description of Engine Condition:

Joe Moore purchased new crankcase from Aero Aviation for his experimental Vari Ez and has been troubleshooting an oil leak since engine went into service. Engine was assembled by Light Speed Engineering.

Recommended Adjustment:

Supply with new crankcase. Parts only no labor and no freight. Return cracked crankcase to TCM for analytical inspection. Warranty is subject to outcome of analytical inspection.

LOG BOOK MUST ACCOMPANY RETURNED ENGINE!

By:

NULL Verify
Bill Ross

Attach File/Image:

Type of Adjustment:

Service Spare

Print AV-18

Back To AV18 Form