




Photo 1 – Main wreckage



Photo 2 – Left wing



Photo 3 – Engine from front after recovery from accident site



Photo 4 – Engine from right side




Photo 5 – Engine case half displaying main bearing scoring and spalling of intake valve tappet faces



Photo 6 – Other case half displaying spalling of intake valve tappet faces



Photo 7 – Camshaft displaying wear to intake valve lobes




Photo 8 – Overview of accident location