



Figure 1 Side view of structural frame damage to helicopter



Figure 2 Severed tail boom



Figure 3 Front view of helicopter with damaged main rotor blades