



Photo 1 – N81GG Hughes 369D (MD 369D) wreckage site (compliments of Maui Police Department)



Photo 2 - Aerial view of wreckage site



Photo 3 - Main rotor and transmission assembly



Photo 4 - Rolls Royce (Allison) 250-C20B engine at accident site



Photo 5 - Wreckage fragments at examination hangar



Photo 6 - Tail rotor drive shaft with fracture and torsional deformation



Photo 7 - Fractured and twisted tail rotor drive shaft



Photo 8 - Main rotor head and transmission



Photo 9 - Rolls Royce 250-C20B engine with drive shafts, pinion gear and couplings



Photo 10 - Five recovered main rotor blades



Photo 11-Tail rotor and vertical stabilizer assembly



Photo 12-Hangar vertical light array




Photo 13-Mechanical pin timer for vertical hangar lights