



NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety
Washington, D.C. 20594

February 21, 2018

AIRWORTHINESS

Group Chairman's Factual Report

WPR17FA128

**Appendix A – Figures
(4 pages)**




Figure 1 – Vans RV-3 3-view drawing



Figure 2 – Wreckage Map



Figure 3 – Lower control stick area with wrench



Figure 4 – Center portion of main wing spar, viewed looking aft



Figure 5 – Corrosion in left upper spar cap layers



Figure 6 – New bolt and bolts removed from left lower spar cap