

Incident Pictures



Figure 1: View of incident airplane's nose gear down-lock actuator piston (note white paint) as provided by the operator.



Figure 2: View of an exemplar airplane's nose gear down-lock actuator piston (note chrome color) as provided by the operator.