



**Photo 1 – Accident site, view of the right main landing gear from the rear.**



**Photo 2 – Accident site, top surface of right wing and right landing gear trunnion.**



**Photo 3 – Accident site, view of right main landing gear from the front.**



**Photo 4 - Accident site, top surface of right wing and right landing gear trunnion.**



**Photo 5 - Accident site, view of the right main landing gear from the rear.**