



Photo 1 – Tail Rotor Gearbox at Accident Site



Photo 2 – Vertical Fin at Accident Site