




Photo 1 – Left wing fuel pump as removed.



Photo 2 – Instrument panel photo immediately after the accident. Courtesy of Bakersfield Airport Management



Photo 3 - Instrument panel photo immediately after the accident. Courtesy of Bakersfield Airport Management



Photo 4 – Instrument panel during wreckage exam.



Photo 5 - Instrument panel during wreckage exam.

