

Photos of N321BJ Belly Damage
Following a gear up landing.



Figure 1: Overall Damage to Belly



Figure 2: Underlying Structure



Figure 3: Exposed Structure

END.

Submitted by Samantha Link