



Photo 1 – view of damaged left propeller blade tip



Photo 2 – view of fuselage damage penetration



Photo 3 – remnants of blade tip at rest in cabin of airplane



Photo 4 – screwdriver as recovered from departure runway