



The induction system hose between the air-box and the turbocharger inlet. The bulge indicated is evidence of delamination (collapse) or the hose that has begun to correct itself due to the elastic properties of the hose material. Any delamination when the turbo was active would quickly result in the airflow coming into the turbo being reduced and therefore the turbocharger unit become ineffective.