

From: [Bill Kelly](#) [REDACTED]
To: [Smith Maja](#)
Subject: RE: Engine Teardown Younkin Aviation
Date: Monday, November 19, 2018 11:34:47 AM

Maja,

I am sorry about the delay getting back to you. As I recall we did inspect the mags for condition, we did not spark them out due to time constraints, although they did rotate when holding them. The carburetor appeared to be normal from just a visual inspection, looking through the venture it appeared clean with no sign of foreign material. Visual of the spark plugs showed signs of normal wear they were not tested.

I hope that helps, again sorry about the delay getting back to you.

Bill Kelly

Aviation Safety Inspector,
AFG-600 Little Rock FSDO

[REDACTED]
Office [REDACTED]
Fax [REDACTED]

Flight Standards Service would appreciate any comments you may have on our services at the following website:
[Comment Here](#)
