



Photo of submerged airplane prior to recovery

Photo 1 – photo of submerged airplane prior to recovery



photo of airplane during recovery process

Photo 2 – photo of airplane during recovery process



Photo 3 – photo of right magneto partially separated from accessory case mount




Photo 4 – photo of missing case bolts




Photo of loose case bolt

Photo 5 – photo of loose case bolt




Photo 6 – photo of failed crank shaft and bearing