

Inspector statement

On April 27, 2018 went to airport 3T6 Aircraft Carburetor and Injector Service. Upon arrival two technicians and I unboxed the carburetor and removed all packaging. A visual inspection of the carburetor showed being slightly dirty with no damage noted.

During disassembly it was noted no safety wired items were missing. Split the carburetor assembly at the mating surfaces all seals were found to be in good condition. Inspected the bowl for cracks none were found. Leak checked the float no leaks were detected no holes were found in the float. Removed inlet screen no debris was found inside the carburetor screen or the carburetor halves. All linkages were found intact and working correctly.

Julius Sutton
Aviation Safety Inspector