



Photo 1 – Light Pole



Photo 2 – Light Pole



Photo 3 – Light Pole



Photo 4 – Taxiway Surface



Photo 5 – Wing Leading Edge Damage