



**Photo 1 – View of the main wreckage.**



**Photo 2 - Area where the tail rotor was located.**



**Photo 3 - Tail rotor as located.**



**Photo 4 - The engine prepared for an engine run.**



**Photo 5 - Magneto bushings located in the oil screen.**