



Photo 1 – view 1 of accident site



Photo 2 – view 2 of accident site



Photo 3 – view 3 of accident site



Photo 4 – view 4 of accident site



Photo 5 – photo of failed vertical anti-torque pedal