



RECORD OF CONVERSATION

Joshua D. Cawthra
Senior Aviation Accident Investigator
Western Pacific Region

Date: October 18, 2017
Person Contacted: Troy Decker (Pilot)
NTSB Accident Number: WPR18LA009

Narrative:

During a telephone conversation, Mr. Decker reported that immediately following the accident, when he attempted to rotate both the left and right main wheels, they would not rotate as if the brakes were engaged. In addition, Mr. Decker reported that he knew the carburetor air inlet temperature display feature was inoperative at the time of the accident.