

On Scene Photos



Figure 1: Overview of Accident Site



Figure 2: Remaining Powerlines



Figure 3: Overall View of Damage



Figure 4: Electrical Wire was found Wrapped around the Main Landing Gear



Figure 5: Powerlines in relation to Approach end of Runway

END.

Submitted by: Samantha Link