


ACCIDENT SITE DIAGRAM

Selma, CA N36° 34' 21" W 1 45' 17"

N88MV

10-30-2017 at 14.19 PDT , VANS RV-6



FAA Photographs – WPR18LA021



Figure 1 - Airplane in Final Location/Position



Figure 2 - Right Side View

FAA Photographs – WPR18LA021



Figure 3 - Empennage



Figure 4 - Left Wing Leading Edge

FAA Photographs – WPR18LA021



Figure 5 - Landing Gear



Figure 6 - Windshield & Canopy

FAA Photographs – WPR18LA021



Cowl

Figure 7 - Propeller



Figure 8 - Instrument Panel



Figure 9 - Alternator Ground Cable Crimp