



RECORD OF CONVERSATION

Albert P. Nixon
Senior Aviation Accident Investigator
Western Pacific Region

Date: December 3, 2017
Person Contacted: Kory Qvigstad
NTSB Accident Number: WPR18LA042

Narrative:

During a conversation with Kory Qvigstad, the following is a summary of what was stated:

- This was the first time he flew with the student pilot.
- After conducting local area work, they were returning to the airport to practice touch and go landings.
- On the first approach to runway 16L, the student pilot was high on the glide path and a go-around was initiated.
- During the go-around about 150 ft above ground level, the engine sputtered and lost power.
- The propeller continued to slow down and then the engine failed.
- He said they were unable to make the runway and elected to land in a nearby field.
- During the forced landing, the airplane hit the ground hard and struck a tree and utility pole.
- Both pilots sustained minor injuries.
- There was about 7 gallons of fuel in each tank when the accident occurred.
- The carb heat was pushed in during the go-around.
- He was seated in the right seat.