



Photo 1 – View of empennage damage (photo courtesy of the FAA).



Photo 2 - View of broken left landing gear saddle (photo courtesy of the FAA).



Photo 3 - View of broken left landing gear saddle after removal (photo courtesy of the FAA).



Photo 4 - View of wreckage on runway (photo courtesy of the FAA).