


N574BR – Prop Hub Failure HTC CCW-3B-172-CG




483 hrs TT on prop.





Clean break to right of red line, not so much to the left of red line














Maintenance entry for prop installation



Separated blade was recovered, spinner removed



Missing portion(s) of hub were not recovered.
New prop was installed and the torque on all bolts
was applied with a non-calibrated torque wrench

