



Photo 1 – Right-rear view of N518Z at the accident site. Photo courtesy of the FAA.



Photo 2 - View of tail boom damage. Photo courtesy of the FAA.



Photo 3 - View of fuselage damage. Photo courtesy of the FAA.



Photo 4 – Right-front view, showing N518Z at the accident site. Photo courtesy of the FAA.



Photo 5 -Right-side view of the engine bay, showing the airframe-mounted fuel filter. Photo courtesy of the FAA.