

WPR18LA215
Photos courtesy Northern Air Inc and USFS



Figure 1 - Airplane on Runway



Figure 2 - Airplane on Runway

WPR18LA215
Photos courtesy Northern Air Inc and USFS



Figure 3 - Aft View of MLG Wells



Figure 4 - Left MLG Door Actuator w Circlip & Rod

WPR18LA215
Photos courtesy Northern Air Inc and USFS



Figure 5 - Right MLG Door Actuator w Circlip & Rod

WPR18LA215
Photos courtesy Northern Air Inc and USFS



Figure 6 - Fuselage Lower Skin Damage



Figure 7 - Fuselage Lower Skin Damage



Figure 8 - Rear Propeller Tip Damage