



Photo 1 – overhead view of accident site looking west up Short Creek (courtesy of Salmon-Challis Forest Service)



Photo 2 – overhead view of accident looking vertically downward (courtesy of Salmon-Challis Forest Service)



Photo 3 – onsite view of wreckage, including cabin/cockpit area, firewall, engine, propeller, bottom of right wing and aileron (courtesy of Salmon-Challis Forest Service)



Photo 4 – onsite view of engine, firewall and propeller (courtesy of Salmon-Challis Forest Service)



Photo 5 – onsite view of engine and empennage wedged in tree (courtesy of Salmon-Challis Forest Service)