



Photo 1 – Accident site, forward view of the main wreckage. (Courtesy of first responders)



Photo 2 - Accident site, view of the forward fuselage and wings during disassembly. (Courtesy of first responders)



Photo 3 - Accident site, left view of the main wreckage during disassembly. (Courtesy of first responders)



Photo 4 - Accident site, view of the forward cabin area. (Courtesy of first responders)



Photo 5 - Accident site, separated propeller assembly. (Courtesy of first responders)



Photo 6 - Accident site, right view of the main wreckage. (Courtesy of first responders)



Photo 7 - Accident site, separated propeller assembly. (Courtesy of first responders)



Photo 8 - Accident site, right view of the main wreckage. (Courtesy of first responders)



Photo 9 - Accident site, left rear view of the main wreckage. (Courtesy of first responders)



Photo 10 - Accident site, left forward view of the main wreckage. (Courtesy of first responders)



Photo 11 - Accident site, forward view of the main wreckage. (Courtesy of first responders)



Photo 12 - Accident site, right side view of the main wreckage. (Courtesy of first responders)



Photo 13 - Accident site, right side of engine assembly. (Courtesy of first responders)



Photo 14 - Accident site, drive shaft separation. (Courtesy of first responders)



Photo 15 - Accident site, engine power and exhaust sections. (Courtesy of first responders)



Photo 16 – Accident site, left wing and side view of wreckage. (Courtesy of first responders)