



Photo 1 – Accident Site



Photo 2 – Right Main Landing Gear and Well



Photo 3 - Empennage



Photo 4 – Accident Site