



Photo 1 – Damage to the Right Wing and Collapsed Landing Gear (Photo Provided by Airport Manager)