



Photo 1 – view of debris field looking northeast



Photo 2 – view of debris field looking southwest toward ELY



Photo 3 – view of debris field looking south



Photo 4 – view of main body of wreckage looking southeast



Photo 5 – view of empennage – horizontal and vertical stabilizers and rudder



Photo 6 – view of separated engine