



Photo 1 – N64RA left-side view.



Photo 2 – N64RA left-front view



Photo 3 – N64RA showing right side of engine and main rotor assembly.




Photo 4 – N64RA showing cargo hook with strap secured in hook.



Photo 5 - N64RA cargo hook on test stand.



Photo 6 - N64RA at exam facility, right-front view.



Photo 7 - N64RA at exam facility left-front view.




Photo 8 - T53-L-13B engine at exam facility, right-side view.



Photo 9- T53-L-13B engine at exam facility, left-side view.




Photo 10 – T53-L-13B engine with large amount of debris resting in the combustion chamber.



Photo 11 – First-stage turbine rotor with a portion of the first stage sealing disk remaining attached.



Photo 12 – First stage sealing disk shown in three fragments. Photo curtesy of Honeywell Aerospace.




Photo 13 – Fragment-end view of the first stage sealing disk. Note the arc-shaped striations consistent with low-cycle fatigue. Photo courtesy of Honeywell Aerospace.