



Photo 1 – N506PH as seen at the accident site. Photo courtesy of the FAA.



Photo 2- N506PH at the accident site. Photo courtesy of the FAA.




Photo 3 – Engine from N506PH, as received at the service center.



Photo 4 - Bleed valve assembly mounted on engine showing valve in the closed position.



Photo 5 – Accident compressor bleed valve assembly, showing corrosion on valve and guide.



Photo 6 – Accident compressor bleed valve, showing corrosion build up on valve stem.



Photo 7 – Bleed valve spring, showing corrosion on top of spring.



Photo 8 – Bleed valve bellows, showing corrosion.