

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 1 - PreAccident Airplane



Figure 2 - First Stump Struck

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 3 - First Stump



Figure 4 - First Stump and Airplane

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 5 - Airplane in Relation to Road

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 6 - Main Wreckage

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 7 - Main Wreckage



Figure 8 - Front View

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 9 - Spinner and Propeller

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 10 - Cowl and Forward Fuselage

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 11 - Cockpit Area



Figure 12 - Cockpit Area

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 13 - Main Wheel

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)




Figure 14 - Propeller Blade Cut in Stump

N215T Photographs – WPR19LA105
(courtesy Grays Harbor County Sheriff and AvTek)



Figure 15 - Propeller