



Photo 1 – Basket and Rigid Frame at Accident Site (Photo Courtesy of Fire Department)



Photo 2 – Corner Plate with intact Eyelet at Accident Site (Photo Courtesy of Fire Department)



Photo 3 – Corner Plate with Elongated Eyelet at Accident Site (Photo Courtesy of Fire Department)



Photo 4 – Corner Plate with Elongated Eyelet Screw at Accident Site (Photo Courtesy of Fire Department)



Photo 5 – Corner Plate with Elongated Eyelet Screw at Accident Site (Photo Courtesy of Fire Department)



Photo 6 – Overview of Rigid Frame (Photo Courtesy of FAA)



Photo 7 – View of Rigid Frame (Photo Courtesy of FAA)




Photo 8 – Close-up View of Eyelet Screws (Photo Courtesy of FAA)



Photo 9 – Nomex Skirt Heat Damage (Photo Courtesy of FAA)