




Memorandum for Record

Fabian Salazar
Air Safety Investigator
National Transportation Safety Board
Investigator in Charge

NTSB Accident Number: WPR19LA255
Aircraft Registration & Make/Model: N1168U / S-58ET
Accident Location: Azusa, California
Accident Date: September 11, 2019

Enclosed are the maintenance records for the tail rotor blade (Serial number 58-HV-27988-28769) that separated from the tail rotor assembly.

[illegible]

Aviation Blade Services, Inc.

51 N. Hoagland Blvd.

Kissimmee, FL 34741

Ph. 407-846-6780

FAA Rep. Stn. #XB7R760J

Part Name: TAIL ROTOR BLADE

Manufacture: SIKORSKY

Part Number S1615-30100-045

Serial Number: 58-HV-27988-28769

New () Overhauled () Repaired (X) Modified () Removed ()

T.T.S.N 885.4

T.S.R. _____

T.T. Remain O/C

Work Order 1817


Purchase Order _____

Vendor _____

The Part identified above was Repaired, Overhauled, and/or Inspected in accordance with current maintenance rules of the FAA and is approved for return to service.

4-20-2007

Date



Authorized Signature



Inspectors Stamp

SERVICEABLE