



Component Analysis Report

N/R = Not Reported / N/A = Not Applicable

Date Received:	02/06/2020	Analytical Date:	03/09/2020								
Warranty Claim #:	N/A	RGA #:	N/A								
Engine Model:	Not reported	Engine Serial #:	Not reported								
Component P/N:	10-682560-11	Component S/N:	D06KA015								
Engine:		Component:	☒	New:		Rebuilt:		Overhaul:		Date:	Not reported
Aircraft Make/Model:	Not reported	Aircraft S/N:	Not reported	Reg. #:	N8353T						
Engine Position:	Single:	☒	Left:		Right:		Front:		Rear:		
Engine Build Date:	Not reported	Date in Service:	Not reported	Date Removed:	Not reported						
Date of Occurrence:	Not reported	Engine/Component Hours:	Not reported								
Inspection Performed By:	Analytical Department	Search Code:	82-26-08								
Party to the Inspection:	Phillip Grice										
Party to the Inspection:	Todd Pryor										
Party to the Inspection:	Randy Bryant										
Components Returned:											
Returned By:	Maja Smith NTSB										
Reason for Return:	Functional Test/ Inspection										
Analytical Report:	Magneto was removed from shipping box. The internal timing was verified. Damage was noted on the mounting flange. The magneto was placed on the test stand and produced spark at each on the twelve leads.										
Comments:											

Engine / Component Disposition			
Release for core salvage:		Date/Sign:	Awaiting Disposition
Customer Name/Company:			
Address:			
City:		State:	
Zip:		Country:	



