

WPR20CA090 Accident Pictures:



Figure 1: Airplane inverted at accident site (right side).



Figure 2: Airplane's damaged tail section (right side).