



Photo 1 – Main wreckage at the accident site.



Photo 2 - Empennage



Photo 3 - Main wreckage at the accident site.



Photo 4 – View of the recovered engine.



Photo 5 - View of the recovered airframe




Photo 6 – View of the internal components of the vacuum pump



Photo 7 - View of the vacuum pump drive shaft



Photo 8 – View of the propeller



Photo 9 – View of the damaged King KI-256



Photo 10 - View of the King KI-256 gyro