



Photo 1 – Push to Talk Switch and Anti-Torque Pedals in Accident Helicopter (Courtesy of Intermountain)



Photo 2 – Damage to Left Side Empennage (Courtesy of Intermountain)



Photo 3 – Closeup of Damage to Left Side Empennage (Courtesy of Intermountain)



Photo 4 – Damage to Tail Rotor Blades (Courtesy of Intermountain)