



RECORD OF CONVERSATION

Albert P. Nixon
Senior Aviation Accident Investigator
Western Pacific Region

Date: September 23, 2020
Person Contacted: Art Granger (A & P Mechanic)
NTSB Accident Number: WPR20LA032

Narrative:

On a conversation with Art Granger, the following is a summary:

- During a gear swing, the landing gear was swung up and down with no anomalies.
- The circuit breaker remained in and the gear extension light was operational.