

On Scene Photos
Courtesy of Local Law Enforcement



Figure 1: Wreckage Debris Path



Figure 2: Left Engine and Main Wreckage



Figure 3: Main Wreckage



Figure 4: The Main Wreckage was Thermally Damaged



Figure 5: Right Engine

END.

Submitted by: Samantha Link