



MEMORANDUM FOR RECORD

Stephen Stein
Aviation Accident Investigator
National Transportation Safety Board
Office of Aviation Safety – Western Pacific Region

NTSB Accident Number: WPR20LA165
Aircraft Registration & Make/Model: N225CK; OMF-100-160
Accident Location: Glendale, Arizona
Accident Date: June 2, 2020

Note: The following interview was documented by the on-call duty officer.

Interview #1 Summary

Bill Willingham
Aircraft Mechanic

Mr. Willingham stated he serviced the accident airplane and had been responsible for signing off the required airworthiness directive (AD) inspections. According to his recount, he complied with the airworthiness directive, but did not look up the manufacturer alert service bulletin (ASB) as was required by the AD. When asked if he knew that the AD required compliance with the ASB he reported that he did not know and that he did not follow the ASB. He added that if the procedures were in the AD he would have followed them.